

PRIORITY
OUT56065

multi
P 282306Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 4850.

1965 JUN 28 23 24Z

Declassification Review by NGA/DoD

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 122 WAS USED IN MISSION 8026 FLOWN ON 25 JUNE 1965.

PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: CHEMICAL SPOTS APPROXIMATELY 0.2" IN DIAMETER ARE LOCATED 8.0" APART AND 3.9" FROM THE INBOARD EDGE OF THE FILM IN FRAMES 001 TO 20. SEVERAL SCRATCHES AT 4.3", 3.7" 2.7", AND 1.0" FROM THE INBOARD EDGE ARE ALSO PRESENT IN THE FIRST 20 FRAMES. A PLUS DENSITY LINE 2.0" FROM THE INBOARD SIDE RUNS CONTINUOUSLY FROM FRAME 027 TO 150 AND THEN BECOMES INTERMITTENT, OCCURRING WITH DECREASING FREQUENCY, UNTIL FINALLY IT IS NOT SEEN AFTER FRAME 1200. PRESSURE ROLLER STATIC IS IN EVIDENCE ALONG BOTH EDGES THROUGHOUT THE MISSION BUT IS CONFINED TO THE OUTER 0.25" ON EACH SIDE. A WAVERING PLUS DENSITY STREAK ABOUT 1.3" FROM THE INBOARD EDGE IS PRESENT INTERMITTENTLY IN THE LAST TWO OF THE ELEVEN PARTS OF THE MISSION. A HEAT SPLICE EXISTS IN THE FORMAT OF FRAME 1239,

29 JUN 1965

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	✓
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

- 2 -

AND MANUFACTURING SPLICES ARE LOCATED IN FRAMES 529 AND 1874.

C. 9L SIDE: MINOR INBOARD EDGE FOG IS EVIDENCED THROUGHOUT THE MISSION. THE VERTICAL POSITION INDICATOR LIGHT WAS INOPERATIVE DURING THE MISSION ON THIS SIDE. MINUS DENSITY DOTS SPACED 0.8" APART ARE LOCATED 1.1" FROM THE OUTBOARD EDGE OF THE FILM IN FRAMES 001 TO 108. FLARE IS PRESENT ADJACENT TO THE DATA CHAMBER IMAGE THROUGHOUT. MYLAR TAPE WAS USED IN MAKING THE BREAKDOWN SPLICE IN FRAME 1230 DUE TO AN IMPROPER CUT DURING PROCESSING. A WAVERING PLUS DENSITY STREAK APPROXIMATELY 1.5" FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT IN FRAMES 1808 TO 2079. A TOTAL OF EIGHT HEAT SPLICES ARE PRESENT BETWEEN FRAMES, AND A MANUFACTURING SPLICE WITH ASSOCIATED HANDLING MARKS IS IN THE FORMAT OF FRAME 556.

D. BOTH SIDES OF THE MISSION CONTAINED TITLED FRAMES NUMBERED FROM 0001 TO 2493.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS IN THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED APPROXIMATELY 25 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--